Oil Field Environmental Incident Summary

Responsible Party: Unknown

Well Operator: Well Name:

Field Name: Well File #:

Date Incident: 3/2/2015 Time Incident: 07:00 Facility ID Number:

County: DUNN Twp: 148 Rng: 94 Sec: 19 Qtr: SE NW

Location Description: Illegal dumping discovered approximately 0.5 miles South of BIA 14 on Oilfield

Road. (47 37' 36.5" N, 102 42' 23.11" W)

Submitted By: Chris Martinez Received By:

Contact Person: Chris Martinez

Unknown

Unknown, ND 00000

General Land Use: Other - Described Above Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Pipeline ROW Reported to NRC: No Spilled Units Recovered Units Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Crude oil and/or produced water - contained within the lease road ROW and immediately adjacent land.

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

No immediate risk, free oil being removed. Contaminated soils to be excavated.

Areal Extent:

~12' x 200' along oilfield road. West side of road.

Potential Environmental Impacts:

No additional spreading of material. Clean up in progress

Action Taken or Planned:

Due to illegal dumping action to take is uncertain.

Wastes Disposal Location:

Agencies Involved: MHA, TAT, BIA, BLM

Updates

Date: 3/2/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred within the MHA Nation boundaries. Forward to BIA/Tribal authorities.